




TWR	118.90, 118.45 (SMC)
APP	120.90, 128.95
RMP	134.1
ATIS	127.6
VOR/DME	114.0



HS 1	AERONAVES EN ATERRIZAJE POR RWY 16/34 DESALOJAR POR TWY "D" Y CONTINUAR HASTA TWY "A" DE ACUERDO A INSTRUCCIONES DEL ATC
	AIRCRAFTS LANDING ON RWY 16/34 MUST VACATE BY TWY "D" AND CONTINUE TO TWY "A" ACCORDING ATC INSTRUCTIONS
HS 2	AERONAVES EN ATERRIZAJE POR RWY 16/34 DESALOJAR POR TWY "E" Y CONTINUAR HASTA TWY "A" DE ACUERDO A INSTRUCCIONES DEL ATC
	AIRCRAFTS LANDING ON RWY 16/34 MUST VACATE BY TWY "E" AND CONTINUE TO TWY "A" ACCORDING ATC INSTRUCTIONS

PRECAUCION CON LOS TRAFICOS EN MOVIMIENTO EN EL TWY "A", "F", "G", "J" Y "K"	CAUTION WITH THE MOVEMENT TRAFFICS ON "A", "F", "G", "J" AND "K" TAXIWAYS
--	---

CABOS
 VOR/DME 114.0
 SJD
 230846N 1094318W



CAMBIOS: FREQ